

SAFETY RECALL

Peli 9410 NiMH Flashlights Can Become Unstable and Explode while Charging, Creating a Risk of Injury

Stop Charging and Using the Flashlight Immediately

	
Peli 9410 Flashlight in Yellow or Black	Peli Replacement Charger Black (9410/9415)

To identify recalled products, check the part on the original packaging, or check the lights logo area, or charger itself.

Contact Peli, 9AM-5PM (CEST), Monday to Friday by phone on +34 93 301 59 94, or via e-mail at support@peli.com to learn more about this recall.

***Note: 9410L & 9415 Z0 are NOT included in this safety recall.**